



The 8th of March 2020

Project No.: SES20863

University of Lethbridge
4401 University Drive West
Lethbridge, AB T1K 3M4

Attention: Michael Pinder

Re: Asbestos Abatement Monitoring Services, University Hall Level 8, D & E Block, Lethbridge, AB

Sherlock Environmental Services Ltd. (Sherlock Environmental) was commissioned by Mr. Michael Pinder of the University of Lethbridge, to carry out abatement monitoring and inspection at the above noted location.

The scope of the project included low risk scraping of drywall joint compound from the windowsills on Level 8 D & E Block. The rooms included: D: 854, 860, 872 and E: 854, 858, 860, 862, 864, 872. Analysis of the air samples provided a final clearance result of <0.01 fibres/cc which is within the specified allowable clearance airborne fibre concentration limit of 0.01 fibres/cc.

The asbestos project was carried out by the University of Lethbridge of Lethbridge, Alberta, on March 4th and 5th, 2020. All work performed on these dates was carried out in accordance with the *Alberta Occupational Health and Safety Act, Chemical Hazards Regulation, 393/88*, and followed the acceptable practices set out in the *Alberta Labour, Asbestos Abatement Manual*. Project notification was submitted to Alberta Workplace Health and Safety.

Details of the project and air monitoring results are provided on the Asbestos Monitoring Reports (Attached).

We would like to thank you for the opportunity to assist you with this project. Please do not hesitate to call us if you have any questions.

Yours very truly,

SHERLOCK ENVIRONMENTAL SERVICES LTD.

Megan Aldous

Megan Aldous
Operations Manager

ASBESTOS INSPECTION DAY SHEET

LOCATION: UHall Level 8, D & E Block University of Lethbridge		DATE: 04-Mar-2020	
CLIENT: University of Lethbridge		JOB# SES20863	
BRIEF DESCRIPTION OF WORK SCOPE: Low-risk scraping of window sills on level 8 D & E block. The scope included the following rooms: D: 854, 860, 872 E: 854, 858, 860, 862, 864, 872			
Daily Tool Box (y/n/na)			
Site Condition General Review			
Active Containment	Y	Safety Boots	Y
Heights	N	Hard Hat	N
Confined Spaces	N	Safety Glasses	N
Work Alone	N	Safety Vest	N
Asbestos	Y	Respirator	Y
Mould	Y	Site Orientation	Y
Chemicals (i.e. Spray Glue, Contaminants):			
Other Hazards (i.e. Slip, Trip, Fall, Heavy Equipment):			
OBSERVATIONS AND WORK ORDERS:			
<p>9:30 Completed HEPA testing on the vacuum to be used for asbestos clean-up. No issues. Reviewed low-risk procedures with Chris from the University. First and second room set-ups visually good. Radiators are covered with poly and the removal areas will be encapsulated with fibrelock after removal. Discussed placing the banner tape lower to act as an invisible wall and discussed having the banner tape across the work zone once work is ready to start and not during set-up when no PPE is required. No additional issues and other procedures are good. Hoping to complete all rooms today.</p> <p>11:00 Inspected room D854. A bit of flaking paint on the underside of the sill and in the South corner the area is visibly wet and suspected visual mould was noted. Discussed the paint with Chris and Mike P is aware of the suspected mould.</p> <p>16:00 Inspected completed rooms (all except E872) and noticed a couple of areas where removal of flaking material could have been better. Some visual debris on the registers and a larger than expected area crumbled from water damage in D860. Will place a monitor in that room to confirm air quality. Room E872 will be completed tomorrow and the NOP has been verified to include March 5.</p>			

LOCATION:	Uhall Level 8 D & E Block University of Lethbridge	DATE(S):	4 - 5 March 2020
CLIENT:	University of Lethbridge	JOB No.:	SES20863

***Note: n.d. indicates no fibres detected in the analyzed sample**