

## ASBESTOS INSPECTION AIR MONITORING RESULTS

LOCATION: UofL C & D Block 4401 University Drive West					DATE(S): 10-Oct-2019			
CLIENT: University of Lethbridge					JOB No.: SES19804			
AIR MONITORING RESULTS (METHOD DETECTION LIMIT IS 0.01 fibres/cc)								
Sample No.	Location	On	Off	Min	L/Min	Vol	Count	f/cc
<b>10-Oct-2019</b>								
19804-1	C570 DCU	9:10	15:00	350	11	3850	2	0.0002548
19804-2	C568 Occupied Office	9:00	15:00	360	11	3960	11.5	0.0014243
19804-3	Hallway Outside C572 & C574	10:00	15:00	300	11	3300	2	0.0002972
19804-4	Field Blank			0		0	0	#DIV/0!
<b>11-Oct-2019</b>								
19804-5	C570 DCU	8:45	12:10	205	11	2255	6.5	0.0014137
19804-6	C568 Occupied Office	8:45	12:10	205	11	2255	4.5	0.0009787
19804-7	Hallway Outside C572 & C574	8:45	12:10	205	11	2255	3	0.0006525
19804-8	C572 DCU	12:10	16:05	235	11	2585	12	0.0022767
19804-9	Hallway Outside C572 & C574	12:10	16:05	235	11	2585	6	0.0011384
19804-10	C574 Occupied Office	12:10	16:05	235	11	2585	3	0.0005692
<b>15-Oct-2019</b>								
19804-11	C572 DCU	8:05	11:45	220	11	2420	9.5	0.0019253
19804-12	Hallway Outside C572 & C574	8:05	11:45	220	11	2420	2.5	0.0005067
19804-13	C574 Occupied Office	8:05	11:45	220	11	2420	2	0.0004053
<b>16-Oct-2019</b>								
19804-14	C572 FINAL	6:00	8:30	150	11	1650	0.5	0.0001486
19804-15	C568 Occupied Office	6:00	8:30	150	11	1650	2	0.0005945
19804-16	Field Blank			0		0	n.d.	#VALUE!
				0		0		#DIV/0!
				0		0		#DIV/0!
				0		0		#DIV/0!
				0		0		#DIV/0!
				0		0		#DIV/0!
				0		0		#DIV/0!
				0		0		#DIV/0!
				0		0		#DIV/0!
				0		0		#DIV/0!
				0		0		#DIV/0!
				0		0		#DIV/0!
				0		0		#DIV/0!
				0		0		#DIV/0!
				0		0		#DIV/0!
				0		0		#DIV/0!
				0		0		#DIV/0!
				0		0		#DIV/0!
				0		0		#DIV/0!
				0		0		#DIV/0!
				0		0		#DIV/0!
				0		0		#DIV/0!